





HIETAKARI®




8/25 5DRLM


Blæk 869/870/871




Parts




1. x1




2. A x1
B x0




3. A x1
B x0



4. A x1
B x2




5. A x1
B x2




6. 6x30 mm




7. 3.5x39 mm




8. x1



9. x2




10. x2




11. x1



12. x2




13. x2



14. x1




15. 4.2x13 mm




16.



17. x1




18. x1



19. x1

Tools



A

$\varnothing 6\text{ mm}$
B


C – Silicone
D – Glue




E





F



G




1




A: 1←5→4→2→3
B: 1←5→4→4→5

A: 1←3→2→4→5
B: 1←5→4→4→5




A






B




2




3







4













6




7



11



9




8




19

2/4

3/5






F



13

10



14