





HIETAKARI®




8/25 6NRLM

S54




Parts




1. x2



2. x2




3. x3




4/83 31RLM




4/83 14RLM




6. x1



7. x1




8. x5




4/83 99RLM

9. x2




10. x1



11. x1

Tools




A

$\varnothing 4$ mm
 $\varnothing 5$ mm
B


C – Silicone
D – Glue




E







F








G






1



2



3



4

