





HIETAKARI®




8/25 5GRLM


Blæk 878/879/880




Parts




1. x1




2. A x2
B x0




3. A x2
B x0



4. A x2
B x4




5. A x2
B x4




6. 6x30 mm




7. 3.5x39 mm




8. x2



9. x4




10. x4




11. x2




12. x2




13. x2



14. x1




15. 4.2x13 mm




16.



17. x1




18. x1



19. x2

Tools



A

$\varnothing 6\text{ mm}$
B


C – Silicone
D – Glue




E



F




G




1




A






B




2




3







4









6






7







11

8






12

9



10



14