





HIETAKARI®




8/25 6PRLM


656




# Parts




1. x1



2. x2




3. x3




4/83 31RLM

4. 5x25mm



4/83 14RLM


5. 3.5x39mm



6. x1




7. x1




8/65 242LM


8. x2



9. x1




10. x1



11. x1




12. x1




4/83 99RLM

13. x1




14. x2


# Tools




A




Ø4 mm  
Ø5 mm  
B




C – Silicone




E






F








G







1







2








4





5



6

