





HIETAKARI®




8/25 0JRLM

718/719/720



Parts



4/83 13RLM

1. 6x30 mm
x16




4/83 11RLM

2. x16




4/83 24RLM

3. x33




1/42 509L2

4. x2




5. x2




6. x1




7. x2



8. x1




9. x2



10. x1



11. x2



12. x1




13. x1



14. x1




15. x1




4/83 23RLM

16. x33

Tools




A




Ø6 mm

B




C – Glue


D – Silicone




E




F




G




H




I







I.




O.







2





8








13

7










10

9



2

